

Day : Thursday
 Date: 6/29/2006

Time: 14:20:24

PALM INTRANET

Inventor Name Search Result

Your Search was:

Last Name = ELZUR

First Name = URI

Application#	Patent#	Status	Date Filed	Title	Inventor Name
09364085	Not Issued	135	07/30/1999	ASSOCIATING A PACKET WITH A FLOW	ELZUR, URI
09364096	6427169	150	07/30/1999	PARSING A PACKET HEADER	ELZUR, URI
09364195	Not Issued	41	07/30/1999	COORDINATING AUTHENTICATION AND ENCRYPTION/DECRYPTION	ELZUR, URI
09364374	6449656	150	07/30/1999	STORING A FRAME HEADER	ELZUR, URI
09364826	Not Issued	71	07/30/1999	A system and technique to process secured services for data in a network	ELZUR, URI
09364835	Not Issued	123	07/30/1999	TECHNIQUE AND APPARATUS FOR PROCESSING CRYPTOGRAPHIC SERVICES OF DATA IN A NETWORK SYSTEM	ELZUR, URI
09365328	6728265	150	07/30/1999	CONTROLLING FRAME TRANSMISSION	ELZUR, URI
09365329	Not Issued	161	07/30/1999	STORING PACKET DATA	ELZUR, URI
09677139	Not Issued	160	09/29/2000	Computer telephony integration adapter	ELZUR, URI
09772732	6621893	150	01/30/2001	COMPUTER TELEPHONY INTEGRATION ADAPTER	ELZUR, URI
10100212	6906978	150	03/19/2002	FLEXIBLE INTEGRATED MEMORY	ELZUR, URI
10173422	Not Issued	41	06/18/2002	Multiple virtual channels for use in network devices	ELZUR, URI
10188377	6629125	150	07/02/2002	STORING A FRAME HEADER	ELZUR, URI
10188378	6629141	150	07/02/2002	STORING A FRAME HEADER	ELZUR, URI

<u>10230643</u>	Not Issued	71	08/29/2002	System and method for identifying upper layer protocol message boundaries	ELZUR, URI
<u>10331302</u>	Not Issued	30	12/30/2002	Receiver-aided set-up request routing	ELZUR, URI
<u>10377833</u>	Not Issued	30	03/03/2003	System and method for expediting upper layer protocol (ULP) connection negotiations	ELZUR, URI
<u>10642023</u>	Not Issued	41	08/14/2003	One shot RDMA having a 2-bit state	ELZUR, URI
<u>10643331</u>	Not Issued	30	08/19/2003	One-shot RDMA	ELZUR, URI
<u>10651459</u>	Not Issued	120	08/29/2003	System and method for handling out-of-order frames	ELZUR, URI
<u>10652183</u>	Not Issued	71	08/29/2003	System and method for TCP/IP offload independent of bandwidth delay product	ELZUR, URI
<u>10652267</u>	Not Issued	122	08/29/2003	System and method for TCP offload	ELZUR, URI
<u>10652270</u>	Not Issued	30	08/29/2003	Method and system for data placement of out-of-order (OOO) TCP segments	ELZUR, URI
<u>10652327</u>	Not Issued	30	08/29/2003	System and method for network interfacing in a multiple network environment	ELZUR, URI
<u>10652330</u>	Not Issued	30	08/29/2003	System and method for network interfacing	ELZUR, URI
<u>10688373</u>	Not Issued	30	10/17/2003	System and method for receive queue provisioning	ELZUR, URI
<u>10688392</u>	Not Issued	30	10/17/2003	System and method for receive queue provisioning	ELZUR, URI
<u>10704891</u>	Not Issued	71	11/10/2003	System and method for managing memory	ELZUR, URI
<u>10727430</u>	Not Issued	30	12/04/2003	Data path security processing	ELZUR, URI
<u>10751732</u>	Not Issued	30	01/02/2004	System and method for handling transport protocol segments	ELZUR, URI
<u>10803719</u>	Not Issued	30	03/18/2004	Self-describing transport protocol segments	ELZUR, URI
<u>10938156</u>	Not Issued	20	09/10/2004	System and method for load balancing and fail over	ELZUR, URI
<u>11126464</u>	Not Issued	30	05/11/2005	Method and system for handling out-of-order segments in a wireless system via direct data placement	ELZUR, URI

<u>11126565</u>	Not Issued	160	05/11/2005	Method and system for wireless transmission control protocol offload engine	ELZUR, URI
<u>11126822</u>	Not Issued	160	05/11/2005	Method and system for processing data segments on-the-fly	ELZUR, URI
<u>11128056</u>	Not Issued	160	05/11/2005	Method and system for controlling offload of connections in a wireless data network	ELZUR, URI
<u>11128065</u>	Not Issued	160	05/11/2005	Method and system for power management during TCP offload	ELZUR, URI
<u>11128071</u>	Not Issued	160	05/11/2005	Method and system for transferring state information during wireless handoff	ELZUR, URI
<u>11253429</u>	Not Issued	19	10/18/2005	Network interface device serving multiple host operating systems	ELZUR, URI
<u>11416717</u>	Not Issued	20	05/03/2006	Network interface device serving multiple host operating systems	ELZUR, URI
<u>60306870</u>	Not Issued	159	07/23/2001	Selective flow control based on multiple virtual channels	ELZUR, URI
<u>60362531</u>	Not Issued	159	03/07/2002	Method of RDMA connection negotiation	ELZUR, URI
<u>60362554</u>	Not Issued	159	03/07/2002	Receiver-aided set-up request routing	ELZUR, URI
<u>60363356</u>	Not Issued	159	03/11/2002	Method of identifying ULP header in TCP stream	ELZUR, URI
<u>60363381</u>	Not Issued	159	03/08/2002	Method of identifying ULP header in TCP stream	ELZUR, URI
<u>60372851</u>	Not Issued	159	04/16/2002	Method for marker based re-segmentation detection	ELZUR, URI
<u>60372852</u>	Not Issued	159	04/16/2002	Method for marker based re-segmentation detection	ELZUR, URI
<u>60403817</u>	Not Issued	159	08/14/2002	One shot RDMA having only a 2 bit state	ELZUR, URI
<u>60404709</u>	Not Issued	159	08/19/2002	Optimizing RDMA for storage applications	ELZUR, URI
<u>60407165</u>	Not Issued	159	08/30/2002	System and method for TCP offload	ELZUR, URI

[Search and Display More Records.](#)

Search Another: Inventor	Last Name	First Name
	<input type="text" value="ELZUR"/>	<input type="text" value="URI"/>
	<input type="button" value="Search"/>	

To go back use Back button on your browser toolbar.